

Supt.report Jan. 2018

1. Plow and sand

2. Fix f550 ford new hub

And rims

3.fix truck284 s cam tube rr

4.open up some ditches and

Tubes had ice in the road

5.we have new cat loader

938m