

Highway report for 09 JAN 19

Vehicles:

- Ford F550 at Matthews Ford: fuel line leaks & checking for leaks under turbo and exhaust manifolds
- 287 Bad turbo

Work accomplished:

- Cleaned up from wind on New Years day
- Temporarily patched 2 culverts Musson Erwin Rd. and Wilbur Hill Rd.
- Put weeper in Somborn Rd.

Discussion:

- #287 Turbo

To do list:

- Replace 4 culverts (3 cross culverts ,1 driveway culverts)
- Evaluate roads for working agreement