

Highway report 6/12/2019

Vehicles:

- Brake work on western Star

Work accomplished:

- Sweeping Roads
- Placed cobbles on outlets of 2 cross tubes on Taylor Road
- Repaired outlet of culvert on Lilley Hill Rd
- Placed Stackable rock in 4 places on Lilley Hill Rd to prevent erosion
- Graded and cut shoulders on ½ Murphy Rd
- Cut Shoulders on ½ mile Oregon Rd
- Replaced 5 driveway tubes on Halbert Hill Rd
- Replaced driveway tube on Oregon Rd (garbage can in hole in culvert for 3 years)
- Cut shoulders and ditches on Gun Club Rd and Ditch Rd prepping for chipseal
- Trimming around signs and guard rails

Discussion: 000

- Flat Iron Bridge Yellow Flag