

Supt.report FEB. 2018

1. Plow and sandING
2. CLEANING THE SHOP
3. NEW FAN BELT ADJUST  
VALVES WESTERN STAR
4. BROKE RUBBER SUSPENSION  
ON FREIGHTLINER
5. TRIMMING BRANCHES THAT  
HANG IN THE ROAD
6. FIXING CHAINS
7. NEW WINDSHIELD CHEVY