

Supt.report mar. 2018

1. Plowing and sandING
2. Clean up tw0 tree in road
3. fix hyd. Hose on the mack
4. chipping brush on baker road
5. pushing back snow bank
6. fix headlights on f0rd 550